



Erase/scale/rotate/toolwidth


The erase command allows you to eliminate an item in your drawing. Use the crosshair to select the item. Item lines will turn red. Right click to end the selection. Answer "YES" to the command line question.




The scale command makes it possible to re-size an item. Use the crosshair, left click to select, right click to end selection. Left click inside the object as the base point. Move the mouse away from the point. Object sizes from small to large.



Rotate an object by using crosshair and left clicking on a line in the object. End selection by right clicking. Select the base point inside the object. Move the mouse around the pivot. Place the object by left clicking. In this example, the object has been copied, moved and rotated.



The toolwidth command displays the path of the cutter, showing the area being cut out by a specific tool diameter. You can see exactly what material will be removed. It is most often used to "dry run" a pattern to see the results on the screen, before cutting. Example of 3 different line sizes.



Type the decimal diameter of the cutter on the command line. Press enter.